

KENNETT TOWNSHIP PUBLIC WORKS DEPARTMENT

TO: Kennett Township Board of Supervisors FROM: Roger Lysle, Public Works Director

Subject: Monthly Report - December

Township Open Space and Basin

The open space including the basin area at the Township was mowed and cleared for the year. Repair and Maintenance is being completed as noted on the Townships inspection report. Minor rutting was filled and the spill way was cleaned. Fallen trees on the lot were cleared.


BACKGROUND: Most failures at pump stations are with pumps breaking down. Having this portable pump as a back up to the backup will allow maintaining the flow during a breakdown eliminating overflows and lowering the probability of DEP fines.





Snow Preparations & Responses:

Residents are reminded not to push snow into the roadway, snow should be pushed/shoveled to the Right of your driveway. The Township is ready for snow events. The salt barns are full and ready for start of the winter snow season. The Road Crew has already responded to early morning salting after rain storms, cold temperature and foggy mornings.



Roadway Shoulder Work:

Shoulder work is being completed throughout the Township including Marshalls Bridge and Rosedale Road.

Chester Water Authority Work:

Chester Water Authority is working on repairing a patch with Hot Mix pavement at Chandler Mill and W. Hillendale Road.

PECO Pole Upgrades:

PECO is doing pole upgrades around the Township. Major tree trimming was completed and new poles were installed so power can be increased. Fairville Road, Old Kennett Road, Burnt Mill Road are some of the roads being upgraded.



Chandler Mill Bridge Rehab:

Chandler Mill Bridge upgrades are set to begin in January and completed by the end of June. The bridge will be removed and taken off site for repair. Although the bridge is closed even to pedestrians now, it is known that walkers and bikers still use the bridge, please help us spread the word that accessing the bridge during construction will not be possible.



MS4 Inspections:

The following basin and outfall inspections were completed for the month, no material deficiencies were reported, and the public works department follows up with property owners who require corrections:

Date	Inspection Type	Location	Location #
12/12/2019	Outfall Inspection	Yorktown Dr	84
12/23/2019	Outfall Inspection	Rosedale Rd	93
12/23/2019	Outfall Inspection	Ways Lane	65
12/26/2019	Outfall Inspection	Sills Mill Rd	101
12/26/2019	Outfall Inspection	Sills Mill Rd	106
12/27/2020	Outfall Inspection	Sills Mill Rd	105
12/27/2019	Outfall Inspection	Sills Mill Rd	124
12/27/2019	Outfall Inspection	Sills Mill Rd	125
12/27/2019	Outfall Inspection	Sills Mill Rd	126



Location 93

PA One Call Responses:

The Road Crew responded to the following PA One Call requests:

Pennsylvania One Call System Response Summary

Responses for KEN as of 1/6/2020 8:42 AM Date Range: 12/01/2019 through 12/31/2019

Ticket Responses	Qty	Percent of Total Responded	Percent of Total Delivered	
CLEAR - NO FACILITIES	45	95.74	95.74	
FIELD MARKED	2	4.26	4.26	
Total Tickets Delivered: 47 Total Responses Received: 47 Response Rate: 100%				

BACKGROUND: PA One call is a system used to prevent damage to underground facilities. To promote safety, we provide an efficient and effective communications network among project owners, designers, excavators, and facility owners. Anyone looking to dig is required to call PA One Call by dialing 811 before digging.